## **LMA District Cover Sheet**

## **Spring 2011 Levee Inspection Results**

## **Reclamation District No. 1601 Twitchell**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)	
* Overall LMA Rating (Fall Only)					
	** Non-receipt of Su	ummer or Winter Inspe	ection Reports may effec	ct overall annual rating.	
* SPRING INSPECTIONS: Overall maintenance deficiencies are rated		nined for the spring ins ria in the spring and in		ual maintenance	
	The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.				
Comments					

#### **Unit Cover Sheet**

## **Spring 2011 Levee Inspection Results**

# **Reclamation District No. 1601 Twitchell**

	Water	way		Bank	Unit Miles
	Unit No. 01 Thre	emile Slough		Left	2.47
	Spring (March - May)	Summer (June - August)	(September - November) Fall		Winter ber - February)
Unit Maintenance Rating (Fall Only)					
Date of Inspection	3/29/2011 - 3/29/2011				
DWR Inspector	Richard Willoughby				
Accompanied By					
Check one:					
project components conditions other that deficiencies identified.  During the current with project components maintenance and the following changes in the comment see the comment see the conditions of the c	vinter (or summer) inspection p identified in the attached Leve in the results of our normal mai ed in the enclosed report. vinter (or summer) inspection p identified in the attached Leve e corrections we have made to in flood project conditions. ction below or on additional she in (Land Side, Water Side, or Co	the Inspection Report by intenance and the correction, my staff or I have been inspection Report by a maintenance deficience beet(s), identify change of	Mile. We have found no chan ections we have made to main e inspected the levee and assorting. In addition to the results cies identified in the report, we of condition by: Start to End Le	ges in flo tenance ociated fl of our no have for	lood project lood ormal und the
Comments					
information must also be	3	eet should be signed an	nd dated by the LMA Represer ch 31 (Winter Inspection). Plea aspection Reports c, Suite 200	ntative ar	nd returned to
~					
X Signature of LMA Repres	sentative		Date		

## Levee Inspection Report By Mile - Spring 2011

# **Reclamation District No. 1601 Twitchell**

Waterway		Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Threemile Slough	Left	2.47	03/29/2011 03/29/2011	Richard Willoughby

LMR	Levee	Mile	Catagony	Item	Loca	Rating	Action/Comment		GPS Latitude/Longitude	
No.	Start	End	Category	пеш	ocation	ing	Action/Comment	Start	End	Photo
1	0.00	2.47	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.122289 ° -121.682501 °	38.087701 ° -121.683766 °	
2	0.00	2.47	Earthen Levee	Vegetation	WS	М	Control annual grass and weeds on the levee slopes and easements.	38.122289 ° -121.682501 °	38.087701 ° -121.683766 °	2
3	0.10	1.31	Earthen Levee	Crown Surface / Depressions / Rutting	CR	М	Regrade the crown roadway for proper drainage.	38.120883 ° -121.682775 °	38.104085 ° -121.683898 °	

\*\* Rating

A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated

C : Corrected W : Watch/Monitor

## Levee Inspection Report By Mile - Spring 2011

# **Reclamation District No. 1601 Twitchell**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Threemile Slough	Left	2.47	03/29/2011 03/29/2011	Richard Willoughby

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	2.47
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking west at a typical	view of the levee.
richard_s_20110215_010.jpg	

Levee Mile Report Line	3
Start Levee Mile	0.10
End Levee Mile	1.31
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Looking north at holes or	n levee crown.

richard\_s\_20110330\_475.jpg

Levee Mile Report Line	3
Start Levee Mile	0.10
End Levee Mile	1.31
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Looking south at crown s	urface rutting.







\* Location

LS: Landside

WS: Waterside

CR: Crown

richard\_s\_20110330\_476.jpg

\*\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated C : Corrected W : Watch/Monitor